MOX[®]

Software Release Note

Software Name: IKS-6728-8Poe Series Firmware

Version No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
3.5	N/A	N/A	IKS-6728-8PoE	N/A	N/A	N/A	"Set Device IP" does not work properly. "Port Flow Control Setting" cannot be configured correctly by web console "Turbo Ring V2 status error" while reboot all device at the same time in linear topology	N/A
3.4	N/A	N/A	IKS-6728-8PoE	N/A	N/A	Add event log for ABC-02-USB configuration backup module Add support for new IM-6700A media modules (available Q3 2014)	1. Potential PoE function errors when fiber modules are inserted 2. Turbo Chain unstable operation after power rebooting 3. Turbo Ring v2 fiber links unstable operation under certain network topology 4. ABC-02-USB configuration export errors 5. "CRC check error" issue when sending IEEE 1588 PTP packets	N/A
3.3	N/A	N/A	IKS-6728-8P0E	1. first version 2. include Turbo Pack 2.	N/A	N/A	N/A	N/A