



## Firmware for NAT-102 Series Release Notes

<b>Version: v1.0.5</b>	<b>Build: 23073117</b>
<b>Release Date: Sep 11, 2023</b>	

### Applicable Products

N/A

### Supported Operating Systems

N/A

### New Features

N/A

### Enhancements

N/A

### Bugs Fixed

- IPV-230306
- The WAN interface loses its connection after a power cycle.
- Connecting the Ethernet port to another device may sometimes cause the link to go down.
- The netmask of the WAN interface is unintentionally changed after rebooting the device.

### Changes

N/A

### Notes

N/A



<b>Version: v1.0.3</b>	<b>Build: 22102112</b>
<b>Release Date: Oct 28, 2022</b>	

### **Applicable Products**

N/A

### **Supported Operating Systems**

N/A

### **New Features**

N/A

### **Enhancements**

N/A

### **Bugs Fixed**

- The system will stop recording Syslog event logs if the device name contains "moxa".
- Users are unable to change the device password when logged in using the default username and password.

### **Changes**

N/A

### **Notes**

This is a beta firmware release for bug fixing only.



<b>Version: v1.0.1</b>	<b>Build: 22033117</b>
<b>Release Date: Apr 06, 2022</b>	

**Applicable Products**

N/A

**Supported Operating Systems**

N/A

**New Features**

N/A

**Enhancements**

N/A

**Bugs Fixed**

- An incorrect interface name (exceeding 12 characters) causes the NAT function to stop working.

**Changes**

N/A

**Notes**

Note: This is a minor firmware update to address the listed bug. If you do not wish to upgrade the NAT-102 firmware, you can also rename the interface to solve this issue.



<b>Version: v1.0</b>	<b>Build: 21111216</b>
<b>Release Date: Dec 24, 2021</b>	

**Applicable Products**

N/A

**Supported Operating Systems**

N/A

**New Features**

- First release.

**Enhancements**

N/A

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A