



Firmware for ICS-G7828A Series Release Notes

Version: v5.7	Build: FWR_ICSG7828A_V5.
Release Date: Feb 17, 2020	

Applicable Products

ICS-G7828A Series

Supported Operating Systems

N/A

New Features

- Supports SFP-10GLRLC-T, SFP-10GZRLC-T, SFP-10GSRLC-T, SFP-10GERLC-T SFP+ modules.

Enhancements

- [MSRV-2017-011][CVE-2019-6561] Supports browser cookie parameters “same-site” to eliminate CSRF attacks.

Bugs Fixed

- The switch failed to recognize the SFP-1GTXRJ45-T SFP module.
- [MSRV-2017-006][CVE-2019-6557] Buffer overflow vulnerabilities that may have allowed remote control.
- [MSRV-2017-007][CVE-2019-6522] An attacker could read device memory on arbitrary addresses.
- [MSRV-2017-009][CVE-2019-6565] No proper validation of user inputs, which allows users to perform XSS attacks.
- [MSRV-2017-011][CVE-2019-6561] CSRF attacks were possible if browser cookie parameters were not correct.
- [MSRV-2017-012][CWE-121] A stack-based buffer overflow condition whereby the buffer that was being overwritten was allocated on the stack.

Changes

N/A

Notes

- MSRV is Moxa's internal security vulnerability tracking ID.



Version: v5.6	Build: Build_18110820
Release Date: Jan 18, 2019	

Applicable Products

ICS-G7828A Series

Supported Operating Systems

N/A

New Features

Layer 3:

- Support tracking function.

Security Related Functions

- System Notification: Definable successful/failed login notification.
- Password Policy: Password strength can be set.
- Account Lockout Policy: Failure threshold and lockout time can be set.
- Log Management: Full log handling.
- Remote Access Interface Enable/Disable.
- Configuration Encryption with password.
- Support SSL certification import.
- Support MAC authentication bypass via RADIUS authentication.
- MAC Address access control list or MAC address filtering.
- Protect against MAC flooding attack by MAC address sticky.
- NTP authentication to prevent NTP DDoS attack.
- Login Authentication: Support primary & backup database servers (RADIUS / TACACS+ / Local Account).
- Login Authentication via RADIUS Server: Support Challenge Handshake Authentication Protocol (CHAP) authentication mechanism.
- RADIUS Authentication: Support EAP-MSCHAPv2 (For Windows 7).
- MXview Security View Feature Support* (with MXstudio V2.4).

Redundancy

- Turbo Ring v2, Turbo Chain Support Port Trunking

Enhancements

- Web GUI supports web browser Chrome 65.0
- CLI: Supports Multiple Sessions (up to six).
- SMTP Supports Transport Layer Security (TLS) Protocol and Removes SSL v2/v3.
- SNMPv3 Traps and Informs.
- Display Issues with Java Applet.
- Fiber Check: Add Threshold Alarm.
- Static Port Lock with VLAN filtering option.
- When GbE Port Speed is [Auto], MDI/MDIX is [Auto] Fixed.
- Web UI/CLI Command Enhancement and Modification.

Bugs Fixed

- Fix abnormal display of packet counter in the web GUI.
- When the device receives large amounts of BPDU packets on a port, the RSTP function does not enable, which might cause the device to reboot.
- If there is an '&' in either the Switch Name or Switch Location column, the description will not display properly on the relevant page.

Changes



- Rate limit adds more options on the ingress rate

Notes

Suggestion:

- Reconfigure the device once you have upgraded to v5.x
- To ensure that the system remains stable, do not export configurations from v4.x or prior into v5.x or later



Version: v4.5	Build: Build_16112110
Release Date: Dec 28, 2016	

Applicable Products

ICS-G7828A-20GSFP-4GTXSFP-4XG-HV-HV, ICS-G7828A-4GTXSFP-4XG-HV-HV, ICS-G7828A-8GSFP-4GTXSFP-4XG-HV-HV

Supported Operating Systems

N/A

New Features

- Add DSCP remark function.
- Add Traceroute function.

Enhancements

- Encrypt all security passwords and keys in web user interface and command-line interface.

Bugs Fixed

- VRRP can't work on RSTP ports.
- VRRP state will be unexpectedly changed when it takes too much time to change IGMP querier.
- VRRP state will be unexpectedly changed when both VRRP Fast Switchover mode is enabled and Port Trunking is set.
- Configurations can't be imported through command line, when VRRP Fast Switchover mode is set with more than 16 entries.
- Device will reboot occasionally when enabling OSPF.

Changes

N/A

Notes

N/A



Version: v4.2	Build: Build_15062312
Release Date: N/A	

Applicable Products

ICS-G7828A-20GSFP-4GTXSFP-4XG-HV-HV, ICS-G7828A-4GTXSFP-4XG-HV-HV, ICS-G7828A-8GSFP-4GTXSFP-4XG-HV-HV

Supported Operating Systems

N/A

New Features

- Add new Multicast Fast Forwarding Mode
- Add new VRRP Fast Switchover Mode
- Add new Multicast Local Route

Enhancements

- Increase IGMP Groups to 4096 (original 1000 groups).
- Improve Turbo Chain link status check mechanism at the head port.

Bugs Fixed

- Device will reboot when using CLI command to backup device configuration to TFTP server.
- Device will reboot when using CLI command to change SNMP v3 data encryption key and the length of key is over than 100 characters.

Changes

N/A

Notes

N/A



Version: v4.1	Build: Build_15030209
Release Date: N/A	

Applicable Products

ICS-G7828A-20GSFP-4GTXSFP-4XG-HV-HV, ICS-G7828A-4GTXSFP-4XG-HV-HV, ICS-G7828A-8GSFP-4GTXSFP-4XG-HV-HV

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- PIM-SM multicast forwarding issues
- Randomly hang issue while booting up
- Topology drawing issue on MXview
- In IGMPv3, fail to forward multicast packets on MSTP DISABLED-STATUS port
- Fail to add Static default route (0.0.0.0/0) through Web console
- Randomly fail to recognize Moxa SFP modules
- In OSPF routing protocol, 10G ports have incorrect path cost
- Randomly fail to connect to ABC-02
- HTTPS certification validity issue
- Reboot issue while TFTP upgrading firmware with incorrect CLI command
- ACL CLI command fail on rules with Ether-type is 0 or IP-protocol is 0
- Hang issue while IGMP join and leave frequently

Changes

N/A

Notes

N/A



Version: v4.0	Build: Build_14093015
Release Date: N/A	

Applicable Products

ICS-G7828A-20GSFP-4GTXSFP-4XG-HV-HV, ICS-G7828A-4GTXSFP-4XG-HV-HV, ICS-G7828A-8GSFP-4GTXSFP-4XG-HV-HV

Supported Operating Systems

N/A

New Features

- First release.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A