

Firmware for ioLogik E1200 Series (E1214) Release Notes

Version: v3.1

Build: Build19110615

Release Date: Nov 26, 2019

Applicable Products

ioLogik E1214, ioLogik E1214-T

Supported Operating Systems

N/A

New Features

- EtherNet/IP registration on Moxa's licensing website is no longer required.
- Added case insensitive content-length for RESTful API.

Enhancements

N/A

Bugs Fixed

- Fixed inaccurate counter value when using Modbus to start a pulse (E1210/E1212/E1213).
- Fixed opposite on/off pulse width display on web console (E1211/E1212/E1214).
- Fixed that the offset scaling value will reset after changing the Alias name (E1260).
- Fixed self-rebooting when entering URL in the browser for the configuration file.
- Fixed EDS file import connection error.
- Fixed failure when using save counter on power failure and reset counter at the same time (E1210/E1212/E1213).
- Fixed inaccurate counter value when using high frequency (E1210/E1212/E1213).
- Fixed that the trap community name is not included in the export file.
- Fixed that EtherNet/IP cannot use the "Set Attribute Single" service.
- Added an enable RESTful API setting in the configuration file.

Changes

N/A

Notes



Version: v3.0

Build: Build17111512

Release Date: Jan 16, 2018

Applicable Products

ioLogik E1214-T, ioLogik E1214

Supported Operating Systems

N/A

New Features

- Added OPTIONS method for RESTful API.
- Added quick access URI for RESTful API.

Enhancements

- Added SNMP Trap Community Setting on web console.
- Mentioned max. 16 characters on password setting page.

Bugs Fixed

- Fixed DHCP lease time did not ask for extension when half of the lease time elapsed.
- Closed IP forwarding function (Port 0).
- Closed UDP Port 161 when SNMP agent is disabled.
- Fixed invalid token issue on login page when using Firefox.
- Fixed RESTful API header case-sensitive issue.
- Fixed invalid token issue on DO setting page.

Changes

N/A

Notes

- This version of firmware works with the ioSearch V2.0 or later only.
- Update only the next or the previous released firmware version to prevent from system failure.



Version: v2.5

Build: Build16091211

Release Date: N/A

Applicable Products

ioLogik E1214, ioLogik E1214-T

Supported Operating Systems

N/A

New Features

- Added EtherNet/IP protocol.
- Added RESTful API.
- Added new registers for Modbus/TCP protocol.
- Added new OIDs of SNMP protocol.
- Modbus, EtherNet/IP, RESTful Services can be disabled (default: enable).
- Added sending heartbeat to 9500 port of MX-AOPC UA Server after heartbeat function is enabled.
- Increased password length from 8 to 16.
- Added checking special character function for preventing from Cross-Site Scripting.
- Changed sending password from GET to POST method.

Enhancements

N/A

Bugs Fixed

- Fixed file transfer with Chrome browser issue (e.g. firmware update, configuration import or export).
- Fixed wrong display ON/OFF width value of pulse mode on channel setting page.

Changes

N/A

Notes



| Version: v2.4 | Build: Build16053018 |
|---|----------------------|
| Release Date: N/A | |
| Applicable Products | |
| ioLogik E1214, ioLogik E1214-T | |
| Supported Operating Systems | |
| N/A | |
| New Features | |
| Improve protocol efficiency with ioLogik 2500 s | eries. |
| Enhancements | |
| N/A | |
| Bugs Fixed | |
| N/A | |
| Changes | |
| N/A | |
| Notes | |
| N/A | |



Version: v2.3

Build: Build15031013

Release Date: N/A

Applicable Products

ioLogik E1214, ioLogik E1214-T

Supported Operating Systems

N/A

New Features

- Support ioLogik 2500 expansion mode.
- Support safe mode auto-clear function.
- Support counter initial value function.
- Support DO Power ON Delay function.

Enhancements

N/A

Bugs Fixed

- Unable to disable the P2P Heart beat interval.
- When the Heart beat Interval Time = 0, the P2P server will reconnect continuously.
- When the P2P client heartbeat is set to a value larger than 256, the time interval will be incorrect.

• When one DI channel mapping to multiple DO channels in P2P mode, the update interval will be fixed.

Changes

N/A

Notes



Version: v2.0

Build: Build13041515

Release Date: N/A

Applicable Products

ioLogik E1214, ioLogik E1214-T

Supported Operating Systems

N/A

New Features

- Support SNMP protocol.
- Add P2P heartbeat function .

Enhancements

N/A

Bugs Fixed

• When power failing, counter storage fail.

Changes

N/A

Notes

- This version of firmware works with the ioSearch V1.5 or later only.
- Use web console when upgrading firmware from V1.0 to V1.10.



| Release Date: N/A Applicable Products ioLogik E1214, ioLogik E1214-T Supported Operating Systems N/A New Features N/A Enhancements • Wording change for DO pulse output . Bugs Fixed N/A Changes N/A Nd N/A N/A Bugs Fixed N/A N/ | Version: v1.10 | Build: Build12010416 |
|---|--|----------------------|
| ioLogik E1214, ioLogik E1214-T Supported Operating Systems N/A New Features N/A Enhancements • Wording change for DO pulse output . Bugs Fixed N/A Changes N/A N/A | Release Date: N/A | |
| Supported Operating Systems N/A New Features N/A Enhancements • Wording change for DO pulse output . Bugs Fixed N/A Changes N/A N/A N/A N/A | Applicable Products | |
| N/A New Features N/A Enhancements • Wording change for DO pulse output . Bugs Fixed N/A Changes N/A N/A | ioLogik E1214, ioLogik E1214-T | |
| New Features N/A Enhancements • Wording change for DO pulse output . Bugs Fixed N/A Changes N/A N/A | Supported Operating Systems | |
| N/A Enhancements • Wording change for DO pulse output . Bugs Fixed N/A Changes N/A N/A | N/A | |
| Enhancements • Wording change for DO pulse output . Bugs Fixed N/A Changes N/A N/A | New Features | |
| Wording change for DO pulse output . Bugs Fixed N/A Changes N/A Notes | N/A | |
| Bugs Fixed N/A Changes N/A Notes | Enhancements | |
| N/A Changes N/A Notes | Wording change for DO pulse output . | |
| Changes N/A Notes | Bugs Fixed | |
| N/A Notes | N/A | |
| Notes | Changes | |
| | N/A | |
| N/A | Notes | |
| | N/A | |



| Version: v1.9 | Build: Build11112413 |
|---|-----------------------------|
| Release Date: N/A | |
| Applicable Products | |
| ioLogik E1214, ioLogik E1214-T | |
| Supported Operating Systems | |
| N/A | |
| New Features | |
| N/A | |
| Enhancements | |
| Ensured system to work properly after | r unstable power condition. |
| Bugs Fixed | |
| N/A | |
| Changes | |
| N/A | |
| Notes | |
| N/A | |



Version: v1.8

Build: Build11092917

Release Date: N/A

Applicable Products

ioLogik E1214, ioLogik E1214-T

Supported Operating Systems

N/A

New Features

- Added Locating I/O function in General Settings.
- Added Modbus address function code=0x08 for "ECHO" function.
- Added Modbus address for Peer-to-peer connection and safe mode status.
- Peer-to-peer connection and safe mode status are displayed on Channels Safe Mode.

Enhancements

- Improved firmware upgrading speed.
- Removed Modbus/TCP ID checking mechanism.

Bugs Fixed

• One DO/AO channel should only be peered by one DI/AI channel.

• No matter safe mode is triggered by Watchdog or Peer-to-peer, the DO/AO status under safe mode should be the same.

Changes

N/A

Notes