



Software Release Note

Software Name: ICS-G7752/50/48 Series Firmware

Version No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
3.4	Build_14122516	N/A	ICS-G7752/50/48 series	N/A	N/A	N/A	1. ABC-01 connectivity Issue	
3.3	N/A	N/A	ICS-G7752/50/48 series	N/A	N/A	1. Add web interface for loop-protection enable/disable 2. Add web interface for SSH/SSL key generation 3. Add web interface/CLI/SNMP for NTP/SNTP client settings 4. Add SNMP MIB for SFP DDM (Diagnostics) 5. Support SFP-1GTXRJ45 10/100/1000 auto-negotiation	1. Login fail in CLI mode when password is with special character 2. Login authentication failed if the radius server does not support privilege levels assignment 3. IEEE 1588 PTP cannot function correctly 4. SFP DDM (Diagnostics) display inaccurate values 5. Configuration import/export fail after firmware upgrade 6. Restricts configuration import if the system name is too long 7. Hybrid VLAN lacks of SNMP MIB object	N/A
3.1	N/A	N/A	ICS-G7752/50/48 series	1. Users can disable "Utility Search", "Telnet Console", "SSH Console", "HTTP Console", and "HTTPS Console", or change the service ports of the above consoles. 2. Support up to 10 user-defined login accounts for consoles	N/A	N/A	1. NTP cannot synchronize time in default setting 2. NTP client function cannot work with Windows XP NTP server 3. Firmware Upgrade Failed when IEEE 802.1x is enabled 4. Switch reboots when receiving IGMP v3 packets (commonly used in Windows 7)	N/A
1.2	N/A	N/A	ICS-G7752/50/48 series	1. Newly released for ICS-G7752/G7750/G7748 series	N/A	N/A	N/A	N/A