



Driver for Windows (Windows 7 2008 R2 or later) Release Notes

| | |
|-----------------------------------|------------------------|
| Version: v3.0 | Build: 20042110 |
| Release Date: May 18, 2020 | |

Applicable Products

CP-118E-A-I/138E-A-I Series, CP-134EL-A-I Series, CP-116E-A, CP-102E/102EL Series, CP-104EL-A Series, CP-168EL-A, CP-132EL Series, CP-114EL Series, CP-118EL-A, CP-102U/102UL Series, CP-104UL/104JU Series, CP-168U Series, POS-104UL Series, CP-132UL Series, CP-134U Series, CP-112UL Series, CP-114UL Series, CP-118U/138U Series, CA-104 Series, CA-108 Series, CB-108 Series, CA-114 Series, CB-114 Series, CA-132/132I Series, CA-134I Series, CB-134I Series

Supported Operating Systems

Windows 10, Windows 7, Windows 8, Windows 8.1, Windows Server 2008, Windows Server 2012, Windows Server 2012 R2, Windows Server 2016, Windows Server 2019

New Features

- Supports Windows Server 2019.

Enhancements

- This driver supports VMware ESXi v6.7.0. The following guest Oses in VMWare ESXi have been tested: Windows 7, Windows 8, Windows 8.1, Windows 10, Windows Server 2008 R2, Windows Server 2012 R2, and Windows Server 2019.

Bugs Fixed

- Interface is reset to default values during a Windows update or when the driver is updated.

Changes

N/A

Notes

N/A



| | |
|-----------------------------------|------------------------|
| Version: v1.24 | Build: 17083014 |
| Release Date: Oct 18, 2017 | |

Applicable Products

CP-118E-A-I/138E-A-I Series

Supported Operating Systems

Windows 10, Windows 7, Windows 8, Windows 8.1, Windows Server 2008 R2, Windows Server 2012, Windows Server 2012 R2, Windows Server 2016

New Features

- Now supports Windows Server 2016.
- Supports PC/104 serial boards, including CA-104, CA-132, CA-132I, CA-108, CA-114, CA-134I, CB-108, CB-114, and CB-134I.

Enhancements

N/A

Bugs Fixed

- Fixed data transmission error in Windows 10 for PCIe cards.
- RTS toggle not working for PCIe boards.
- While installing PC/104 and ISA cards, the model name might not be found when using the “Add New Hardware Wizard”.
- Software kept cancelling read commands, which caused a BSOD.
- When the system boots up with CP134EL-A-I, CP138E-A-I, CP118E-A-I, and CP-116E-A, serial communication might fail randomly.

Changes

N/A

Notes

N/A



| | |
|-----------------------------------|-------------------|
| Version: v1.24 | Build: N/A |
| Release Date: Oct 18, 2017 | |

Applicable Products

N/A

Supported Operating Systems

Windows 10, Windows 7, Windows 8, Windows Server 2008, Windows Server 2012

New Features

N/A

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A