

Firmware for EDR-G9010 Series Release Notes

Version: v2.1 Build: 22122916

Release Date: Jan 09, 2023

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- IPsec over L2TP behaves abnormally if IPsec settings have been configured previously.
- Static routing does not work properly after enabling dynamic routing.
- The OSPF current router ID displays incorrectly after rebooting the device.
- The Turbo Ring becomes unstable after enabling the NTP/SNTP server.

Changes

N/A

Notes



Version: v2.0.1 Build: 22101419

Release Date: Oct 20, 2022

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Layer 3-7 firewall policies behave abnormally after deploying the policy profile through MXsecurity.
- The system is unable to get the MXsecurity Agent Package information after booting the device.
- Users are unable to import configurations after changing the event log threshold settings.

Changes

N/A

Notes



Version: v2.0 Build: 22092310

Release Date: Sep 26, 2022

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added support for Intrusion Prevention System (IPS) functionality through network security packages.
- Added support for the MXsecurity management software through MXsecurity agent packages.
- Added NAT Advanced Settings.
- Added Session Control Firewall Policy settings.

Enhancements

- Updated the web user interface to the latest next-generation design.
- Layer 3-7 firewall policies are now object-based for better rule management.
- Improved firewall log categories and information layout for better readability.

Bugs Fixed

N/A

Changes

N/A

Notes



Version: v1.2 Build: 22032514

Release Date: Mar 29, 2022

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

• Added support for built-in security packages.

Enhancements

• Increased the maximum number of static multicast routes from 32 to 256.

Bugs Fixed

• Exporting static multicast rules fails when the Static Multicast Route function is disabled.

Changes

N/A

Notes



Version: v1.1 Build: 21110913

Release Date: Dec 02, 2021

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

- Added support for the EDR-G9010 high-voltage (HV) models.
- Added support for the Turbo Ring V2 Coupling mode Layer 2 redundancy protocol.
- Added support for MSCHAPv2 authentication for RADIUS servers.

Enhancements

• Improved the phrasing of package control operation error messages.

Bugs Fixed

- CVE-2021-33909: vulnerability issue.
- The firewall and DoS event logs show incorrect information.
- Importing device configuration may fail under certain conditions.
- The local user database is invalid if RADIUS is disabled.
- The Drop Malformed Packets firewall function behaves irregularly when accessing the web UI.
- The web UI crashes when exporting the log file while the Malformed Packet function is enabled.
- HTTP would generate an error after upgrading the firmware.
- Enabling or disabling HTTPS(443) will disconnect users from the web UI.

Changes

N/A

Notes



Version: v1.0 Build: 21052417

Release Date: Jun 22, 2021

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

The first release of the EDR-G9010 series.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes