



## Firmware for OnCell 3120-LTE-1 Series (US models, HW Rev. 1.0.0) Release Notes

|                                   |                        |
|-----------------------------------|------------------------|
| <b>Version: v1.6</b>              | <b>Build: 21081110</b> |
| <b>Release Date: Aug 11, 2021</b> |                        |

### Applicable Products

OnCell 3120-LTE-1-US (HW Rev. 1.0.0), OnCell 3120-LTE-1-US-T (HW Rev. 1.0.0)

### Supported Operating Systems

N/A

### New Features

- Added the WAN Backup function to provide WAN failover between the cellular and Ethernet interfaces for serial-to-Internet applications.
- Added support for an IPv6 management IP address to access the device's web console.
- Added the cellular MTU (Maximum Transmission Unit) setting to the web console.
- Added support for SHA-256 and SHA-512 hash algorithm options for OpenVPN connections.

### Enhancements

- Increased the maximum port forwarding rules from 32 to 128.
- The connection to OnCell Central Manager (software v2.4.1 or higher) now supports SSL.

### Bugs Fixed

- Clicking Submit on the Syslog Event Types settings page generates an error message (Invalid input: "(syslog power)").
- The self-signed SSL certificate is absent after the device is reset to factory defaults.
- (CVE-2021-3156) Sudo before 1.9.5p2 contains a heap-based buffer overflow.

### Changes

- Renamed "Operation Mode" to "Serial Operation Mode" and is now under "Serial settings".

### Notes

- This firmware release is only applicable to US models with HW Rev. 1.0.0.



|                                   |                        |
|-----------------------------------|------------------------|
| <b>Version: v1.4</b>              | <b>Build: 20122212</b> |
| <b>Release Date: Jan 19, 2021</b> |                        |

### **Applicable Products**

OnCell 3120-LTE-1-US-T, OnCell 3120-LTE-1-US

### **Supported Operating Systems**

N/A

### **New Features**

Added support for NAT Loopback by default for Port Forwarding.

### **Enhancements**

N/A

### **Bugs Fixed**

N/A

### **Changes**

Changed the default setting of the “Cellular WAN Interface” to “Enable”.

### **Notes**

N/A



|                                   |                        |
|-----------------------------------|------------------------|
| <b>Version: v1.1</b>              | <b>Build: 20111610</b> |
| <b>Release Date: Nov 18, 2020</b> |                        |

**Applicable Products**

OnCell 3120-LTE-1-US-T, OnCell 3120-LTE-1-US

**Supported Operating Systems**

N/A

**New Features**

- First release.

**Enhancements**

N/A

**Bugs Fixed**

N/A

**Changes**

N/A

**Notes**

N/A